
Replacement Sheet





1/2

FIG. 1

Replacement Sheet

•

.

ì

,

2/2





FIG. 2




. .

150

160

JAN-1 8 2005



TE TEST FAILS (PROBLEM IN THE CIRCUIT) MAGNET IN PLACE WILL NOT ALLOW RELAY TO RESET OR CLOSE.

Fig.1

,90

## Annotated Marked-Up Drawings

· ·




Fig. 2